

















PARTS LIST:


A  Headboard=1pc	B  Footboard=1pc	C  Supporting block on SR=2PCS
D  Siderail=2pcs	E  Support block on footboard=1PC	F  Metal side support rail=2PCS
G  Support block on headboard=1PC	H  Metal Centre cross rail=1PC	I  Non-woven fabric=1PC
J  Metal block=2PCS	K  Metal corner block=2PCS	L  Fabric Handle=1PC
M  Slat=16PCS	N  End cap=32PCS	O  Gas Lift Mechanism=2PCS
P  Metal Centre cross rail=1PC		

HARDWARE LIST:


1 Allen Key $\varnothing 5/16"$ = 1pc 	2 Bolt $\varnothing 5/16"$ X $3/4"$ L = 20 pcs 	3 Bolt $\varnothing 5/16"$ X $1-1/2"$ L = 16 pcs 
4 Bolt $\varnothing 5/16"$ X $2"$ L = 4 pcs 	5 Flat Washer $\varnothing 5/16"$ X $\varnothing 19$ mm = 48 pcs 	6 Spring Washer = 48 pcs 
7 Nut = 4 pcs 	8 Wrench = 1pc 	9 Nut = 4 pcs 
10 Bolt $\varnothing 5/16"$ X $1"$ L = 8 pcs 		




step 4




step 6




step 5




step 7



step 8



step 9



step 10

